HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Catawissa Bridge
Spanning the North Branch of the Susquehanna
River at State Route 42
Catawissa
Columbia County
Pennsylvania

HAER No. PA-90

Photograph	er: Clen Edwards June-July 1984
PA-90-1	FAST FLEVATION OF SITE
PA-90-2	EAST ELEVATION
PA-90-3	EAST ELEVATION OF EAST PIER
PA-90-4	HANDRAIL AND TIMBER SIDEWALK ON NORTH (UPSTREAM) SIDE OF FAST SPAN (AT MIDSPAN)
PA-90-5	TRUSS JOINT L7, FAST SPAN, UPSTREAM SIDF
PA-90-6	TRUSS JOINT L5, EAST SPAN, UPSTREAM SIDF
PA-90-7	TRUSS JOINT L4, EAST SPAN, UPSTREAM SIDE
PA-90-8	TRUSS VERTICAL MEMBER L1-U1, EAST SPAN, DOWNSTREAM SIDE
PA-90-9	TRUSS JOINT UI, UPPFR CHORD, EAST SPAN, DOWNSTREAM SIDE
PA-90-10	TRUSS JOINT U3, UPPER CHORD, EAST SPAN, DOWNSTREAM SIDE
PA-90-11	TRUSS JOINT U4, UPPER CHORD, FAST SPAN, DOWNSTREAM SIDE
PA-90-12	TRUSS VERTICAL MEMBER L6-U6 AT COUNTER CONNECTION AT MIDHEIGHT, EAST
	SPAN, DOWNSTREAM SIDE
PA-90-13	TRUSS LOOKING FAST FROM JOINT L6'IN EAST SPAN
PA-90-14	TRUSS VERTICAL MEMBER L7-U7 AND UPPER CHORD MEMBER U7-U6', EAST SPAN,
	DOWNSTREAM SIDF
PA-90-15	TRUSS VERTICAL MEMBER L7-U7 AT STRUT CONNECTION, EAST SPAN,
	DOWNSTREAM SIDE
PA-90-16	NORTH (UPSTREAM) ELEVATION OF EAST SPAN
PA-90-17	SOUTH ELEVATION OF EAST PIFR
PA-90-18	NORTH ELEVATION OF SECOND (FROM EAST) SPAN
PA-90-19	NORTHEAST RETAINING WALL AT EAST ABUTMENT (FROM NORTH)
PA-90-20	DETAIL OF NORTHEAST RETAINING WALL
PA-90-21	DETAIL OF NORTHWEST CORNER OF EAST ABUTMENT
PA-90-22	WEST FLEVATION OF FAST ABUTMENT
PA-90-23	SOUTHWEST CORNER OF EAST ABUTMENT
PA-90-24	ROAD WAY STRINGERS AT EAST ABUTMENT
PA-90-25	TRUSS JOINT LO AT BEARING, EAST SPAN, DOWNSTREAM SIDF
PA-90-26	FLOORBEAM AT JOINT LI, EAST SPAN, LOOKING SOUTHWEST
PA-90-27	FLOORBEAM CONNECTION AT JOINT L1, FAST SPAN, DOWNSTREAM SIDE
PA-90-28	PORTAL BRACKET AT MEMBER LO'-U1', EAST SPAN, DOWNSTREAM SIDE
PA-90-29	WEST ELEVATION OF SITE
PA-90-30	WFST ELEVATION
PA-90-31	SOUTH (DOWNSTREAM) ELEVATION OF BRIDGE
PA-90-32	TRUSS JOINT LO' AT BEARINC, WEST SPAN, DOWNSTREAM SIDE
PA-90-33	TRUSS JOINT 14, WFST SPAN, UPSTREAM SIDE
PA-90-34	TRUSS JOINT L5, WEST SPAN, UPSTREAM SIDF
PA-90-35	TRUSS JOINT L7, WEST SPAN, UPSTREAM SIDE
PA-90-36	FLOORBEAM CONNECTION AT JOINT L1, WEST SPAN, DOWNSTREAM SIDE
(Continued)	

Catawissa Bridge HAER No. PA-90 (Page 2) Index to photographs

- PA-90-37 TRUSS JOINT U1, UPPER CHORD, WEST SPAN, DOWNSTREAM SIDE
- PA-90-38 TRUSS JOINT U5, UPPER CHORD, WEST SPAN, DOWNSTREAM SIDE
- PA-90-39 TRUSS VERTICAL MEMBER L6'-U6' AT COUNTER CONNECTION AT MIDHEIGHT, WEST SPAN. DOWNSTREAM SIDE
- PA-90-40 TRUSS LOOKING EAST FROM JOINT L6'IN WEST SPAN
- PA-90-41 SOUTH (DOWNSTREAM) ELEVATION OF WEST SPAN
- PA-90-42 SOUTHEAST CORNER OF WEST ABUTMENT
- PA-90-43 FAST FLEVATION OF WEST ABUTMENT
- PA-90-44 NORTH ELEVATION OF WEST ABUTMENT AND RETAINING WALL
- Photocopies of Photographs from A History of Catawissa Pennsylvania, Mrs. Jeanne R. Roberts and Rev. John R. Albright, Co-Editors, 1974
- PA-90-45 "TWO SPANS OF THE BRIDGE COLLAPSED IN THE FLOOD OF 1904", MARCH 1904
- PA-90-46 "REBUILDING THE BRIDGE AFTER THE 1904 FLOOD," WINTER 1905-1906
- Photocopies of orginal drawings in the collection of the Pennsylvania Department of Transportation Engineering District 3-0 files
- PA-90-47 PLAN SHOWING SURVEY FOR BRIDGE AT CATAWISSA, PA, NOVEMBER 8, 1904
- PA-90-48 GENERAL LOCATION AND DETAILS OF MASONRY, JANUARY 31, 1905
- PA-90-49 NEW SUPERSTRUCTURE, JANUARY 31, 1905
- PA-90-50 FLOOR AND SIDEWALKS FOR EXISTING TRUSSES, JANUARY 31, 1905
- PA-90-51 RAIL INSULATION CATAWISSA BRIDGE, OCTOBER 9, 1905
- PA-90-52 PROPOSED REPLACEMENT OF BRIDGE FLOOR, MAY 8, 1936
- PA-90-53 WIRE FACILITIES ON BRIDGE, AUGUST 2, 1937,
- PA-90-54 REPAIR PLANS DATED AUGUST 3, 1937, SHEET 2 OF 5
- PA-90-55 SHEET 3 OF 5
- PA-90-56 SHEET 4 OF 5
- PA-90-57 SHEET 5 Of 5
- PA-90-58 ATTACHMENT DETAILS FOR BELL TELEPHONE CABLE, DECEMBER 8, 1937